

# Glair G34 Series

## High Solid Special Effects Polyurethane



**Product** Glair G34 Series High Solid Special Effects Polyurethane

**Item Class** High Solid Polyurethane Topcoat

Glair G34 Series is a high solid polyurethane decorative coating formulated to provide superior resistance and astonishing appearance. With unlimited mica and pearlescent color options available, various special effects may be achieved with this system. This product is also formulated to surpass conventional polyurethanes with superior chemical resistance and flexibility.

**Specifications** Product is manufactured to meet the performance requirements of the following specifications:

AMS 3095\* - AIMS 04.04.025 - AIMS 04.04.031 - AIMS 04.04.032 - BAMS 565-002 Class A, Grade B - BAMS 565-009 Type I, Class A, Grade B - DHMS C4.04 -MIL-PRF-85285E, Ty I-IV Cl H - MEP 10-069

\*(On QPL Listing) – Please check 3chem.com for complete specification list

**Catalyst & Additives** Catalyst/Activator Additive

305	PS40 Accelerator
*AVAILABLE IN VARIOUS KIT SIZES	

**Use of Primers** 3Chem recommends use of P1019 (High Solid Epoxy Primer) with this system. Please contact your local 3Chem representative for a complete list of epoxy primers which may be utilized with this system.

**Surface Preparation** Prepare substrate per OEM requirements. Refer to Glair application guide for detailed instructions or contact your local 3Chem representative for assistance.

**Mixing Instructions**

Base	Catalyst/Activator	Mix Ratio
G34-XXXX	305	1:1

Shake (Base) for 15 minutes to assure no solid settlement remains in can. Add component B catalyst to component A paint first. Mix ratio for material is 1 part component A paint, 1-part component B catalyst. No thinner should be added. (Kit yield either 2 gallons or 2 quarts).

**Induction Time** Although no induction time is needed. Once mixed together, insure that admixed material is continuously stirred for at least 5 minutes before proceeding.

**Spraying Viscosity** 17-21 Seconds with #2 Zahn cup

# Glair G34 Series

## High Solid Special Effects Polyurethane



**Pot Life** 7 Hours @ 21° Celsius, 70° Fahrenheit

**Film Thickness** 2-3 MILS DFT (2 Coats @ 1-1.5 DFT) Wet film thickness should be 4-6 MILS total between 2 coats

### Application Instructions

Temperature and Humidity	Minimum	Maximum
Temperature Celsius	11°	35°
Temperature Fahrenheit	52°	95°
Humidity	33%	74%

#### Spray Equipment

Spray Gun Type	Tip/Nozzle Size	Cap Pressure	Pot Pressure
Conventional Air	1.3 - 1.6 mm	40 to 60 psi	10 to 20 psi
HVLP	1.4 - 1.6mm	10 psi Maximum	10 to 20 psi
Electrostatic	1.2 - 1.5mm	45 to 60 psi	10 to 40 psi

#### Dry Time

Temperature	Wet-Edge	Time Between Coats	Dry to Tape	Dry to Handle	Full Cure
52-65°F (11-18°C)	40 Min	30-50 Min	5-6 Hours	7-8 Hours	6 Days
66-85°F (19-29°C)	35 Min	30-45 Min	5-6 Hours	7-8 Hours	6 Days
86-95°F (30-35°C)	30 Min	30-40 Min	6-7 Hours	7-8 Hours	6 Days

#### Dual-Coat Colors (Aluminums, Blacks, Blues, Greens, Oranges, Reds, Silvers, and Yellows):

Only mix enough material to be used on initial application. Always add component B activator to component A paint. Complete kit of material will yield 2 US Gallons (7.5 liters). 1-gallon component A paint, 1-gallon component B activator.

Apply one even wet coat of material using a uniform spray pattern. Apply second coat immediately after completing first coat using 50% less material. Final appearance is the direct result of air and material volume used by the applicator.

Once G34 Series Special Effects Coat is tack dry (refer to dry time schedule on this document), apply one even wet coat of G31-1004 High Solid Polyurethane Clear Coat. A second cross coat may be applied to achieve additional depth in final appearance.

#### Tri-coat Colors (Whites and Grays, these colors require a 3-step application process):

Prior to applying G34 Series Special Effects Coating, a single wet coat of G32 Series semi-gloss base coat (of corresponding color) must be applied to substrate in order to achieve required coverage. Minimum coat thickness should be .8 mil DFT. Once product is tack dry with zero paint transfer, the following steps may be taken.

Only mix enough G34 Series material to be applied on initial coat. Always add component B activator to component A paint. Complete kit of material will yield 2 US Gallons (7.5 liters). 1-gallon component A paint, 1-gallon component B activator.

Apply one even wet coat of material using a uniform spray pattern. Apply second coat immediately after completing first coat using 50% less material. Final appearance is the direct result of air and material volume used by the applicator.

# Glair G34 Series

## High Solid Special Effects Polyurethane



Once G34 Series Special Effects Coat is tack dry (refer to dry time schedule on this document), apply one even wet coat of G31-1004 High Solid Polyurethane Clear Coat. A second cross coat may be applied to achieve additional depth in final appearance.

### **Application Instructions** PS40 Accelerator (Fast dry additive mix options)

PS40 Accelerator	Dry Between Coats	Dry to Handle	Dry Hard	Pot Life	Full Cure
2% By Volume	12 Minutes	2 Hours	4 Hours	4 Hours	6 Days
3% By Volume	10 Minutes	1.5 Hours	3 Hours	3 Hours	6 Days
5% By Volume	5 Minutes	45 Minutes	1 Hour	45 Minutes	6 Days

\*Note: Overuse of PS40 additive may affect product gloss and finish

**Theoretical Coverage** 800-900 sq. ft / gallon @ 1 mil 20-22m<sup>2</sup> / liter @1 mil  
\*Coverage based on 100% transfer efficiency rate

**Color** Available in all color ranges

**Gloss** 80-90 @ 60 degrees (Prior to G31 Series clear coat application)

**Volatile Organic Compound** 340 – 390 g/l

**Shelf Life** 24 Months (When stored in climate-controlled environment between 60-80° F)  
\*Product may be re-certified upon inspection by 3Chem.

**Safety Instructions** Always read material safety data sheet (SDS) and product label before utilizing this product. Product SDS is available upon request.

#### 3Chem Corporation Disclaimer

All information, recommendations, statements, and technical data contained herein are not intended to be comprehensive or exhaustive, but instead are based on tests utilizing present knowledge and current laws. The accuracy and completeness of said tests are in no way guaranteed, nor should they be construed as an express or implied warranty. We believe such information, recommendations, statements, and technical data to be reliable and accurate, but we have no control over the quality or the condition of the many factors affecting the use and application of the product. The user shall depend upon its/his/her own information, data and testing to determine whether the product is suitable for the user's intended use and the user assumes all risks and liability resulting from its/his/her use of the product. Seller's and manufacturer's sole responsibility shall be to replace that portion of the product of this manufacturer which proves to be defective. Neither seller nor manufacturer shall be liable to the buyer or any third person for any injury, loss, or damage directly or indirectly resulting from use of, or inability to use, the product. Recommendations or statements other than those contained in a written agreement signed by an officer of the manufacturer shall not be binding upon the manufacturer or seller. All products supplied, and technical advice given is subject to our standard terms and conditions of sale. The information contained in this data sheet is subject to modification from time to time in the light of experience and our policy of continuous development. It is the user's responsibility to verify that this data sheet is current prior to using the product.

\*Brand names mentioned above are either trademarks of or licensed to 3Chem Corporation.